

About the Tall Buildings Safety Strategy

The Tall Buildings Safety Strategy was authored by the Applied Technology Council (ATC), a non-profit whose mission is to provide state-of-the-art, user-friendly engineering resources and applications for hazard mitigation. ATC convened a team of seismic engineering experts to address different aspects of the study.

An Executive Panel that included the City Administrator, Chief Resilience Officer, Department of Building Inspection, Department of Emergency Management, and the Public Utilities Commission oversaw the study. Key stakeholders representing elected officials, private engineers and architects, developers, community organizations, and city officials met on two occasions to receive updates on the study's progress and provide feedback.

A copy of the recommendations developed from the strategy is available online at: onesanfrancisco.org/resilient-sf.

The Tall Buildings Safety Strategy adds to San Francisco's many innovative programs and initiatives to improve the City's preparedness and ability to recover in the event of a major earthquake and strengthens the integrity and resilience of the City's infrastructure, neighborhoods, and residents. It follows and considers such leading efforts as the Building Occupancy Resumption Program (BORP), established to help building owners pre-certify private post-earthquake inspections and facilitate safe reoccupancy; the Community Action Plan for Seismic Safety (CAPSS), a report to understand and mitigate earthquake risks; and the Earthquake Safety Implementation Program (ESIP), a thirty-year work plan and timeline created in 2011 for implementing CAPSS. It complements the Mandatory Soft Story Program and Private School Evaluation as initiatives undertaken to evaluate and retrofit our buildings ahead of the next large earthquake.

Questions about the Tall Buildings Strategy should be directed to Danielle Mieler, Principal Resilience Analyst, Office of Resiliency and Capital Planning at Danielle.Mieler@sfgov.org or (415) 554-4540.











Putting Safety and Resilience First

The initial release of the recommendations from San Francisco's Tall Buildings Safety Strategy in October 2018 marked a pioneering effort. The first of if its kind, nationally and internationally, the publishing of the Tall Buildings Safety Strategy represented 14 months of citywide collaboration to close the data gap on San Francisco's tall building stock and provide the City with the key information needed to think collectively and proactively about the seismic safety and resiliency of these highly complex structures.

Implementation of the recommendations will take a coordinated effort by the City as well as by the community. We welcome the critical conversations ahead as we consider the necessary steps to ensure the safety for all who come to San Francisco to live, work, and visit. By engaging in a public dialogue, earthquake preparedness becomes a shared priority for all San Franciscans so that we may respond quickly together toward recovery and re-occupancy after the next big earthquake.

We expect that some of the choices on how to best implement the recommendations will be difficult. The recommendations of the Tall Buildings Safety Strategy, prepared by seismic and engineering experts of the non-profit Applied Technology Council, were finalized in January 2019. Though the recommendations stem from a comprehensive study of San Francisco's 156 existing and permitted tall buildings, they also may be applicable to a wider network of buildings.

Following the release of the full study, Mayor London N. Breed issued Executive Directive 19-01: Improving Resiliency in San Francisco's Tall Buildings for Future Disaster on January 23, 2019. The Executive Directive further confirms that our best line of defense against the adverse effects of the next big earthquake is to prepare and strengthen the integrity and resiliency of the city's infrastructure, neighborhoods, and residences while engaging our community members and stakeholders throughout the process. The Mayor's Executive Directive builds upon San Francisco's tradition of consensus building and science-based decision making to anticipate and mitigate earthquake risks.

According to the U.S. Geological Survey, it is estimated that San Francisco has a 72 percent chance of experiencing a 6.7 magnitude or greater earthquake before 2043. We are grateful for the commitment of our city departments, elected officials, and residents as we continue to hold important public discourse in supporting a safe, resilient, and vibrant San Francisco.

Sincerely,



Naomi Kelly City Administrator



Mary Ellen Carroll
Executive Director
Department of
Emergency Management



Tom Hui
Director
Department of
Building Inspection

Table of Contents

- **5 Executive Directive 19-01:** Improving Resiliency in San Francisco's Tall Buildings for Future Disaster
- **8** Summary Recommendations

12 1. Actions for Reducing Seismic Risk Prior to Earthquakes – New Buildings

- 1A. Develop Regulations to Address Foundation and Geotechnical Issues
- 1B. Establish Recovery-Based Seismic Design Standards

2. Actions for Reducing Seismic Risk Prior to Earthquakes – Existing Buildings

- **2A.** Apply the Repair Provisions of the San Francisco Existing Building Code with Respect to Possible Loma Prieta Damage
- 2B. Amend the San Francisco Existing Building Code Triggers
- **2C.** Recommend Minimum Levels of Earthquake Insurance or Other Collateral to Ensure Post-earthquake Recovery
- 2D. Review Requirements for Post-earthquake Fire Suppression and Evacuation Systems

20 3. Actions for Reducing Seismic Risk Following Earthquakes

- **3A.** Develop New Policies and Procedures for Implementing the State's Safety Assessment Program
- **3B.** Extend and Improve the Building Occupancy Resumption Program
- **3C.** Clarify and Update Roles and Responsibilities Associated with Post-earthquake Emergency Response and Safety Inspection
- 3D. Update and Amend the San Francisco Existing Building Code Triggers for Repair Projects
- **3E.** Update Administrative Bulletin 099 and Clarify its Application to Tall Concrete Structural Systems
- **3F.** Develop a New Administrative Bulletin for Post-earthquake Inspection and Evaluation of Welded Steel Moment Frames
- **3G.** Create Protocols and Procedures for Establishing Cordons around Damaged Buildings
- **3H.** Require Existing Buildings to File Recovery Plans

4. Actions to Improve the City's Understanding of Its Tall Building Seismic Risk

- **4A.** Maintain and Expand the Database of Tall Buildings
- **4B.** Develop a Comprehensive Recovery Plan for the Financial District and Adjacent Neighborhoods
- **30 Summary Tables**

38 Tall Buildings Safety Strategy Stakeholders



Executive Directive 19-01:

Improving Resiliency in San Francisco's Tall Buildings for Future Disaster

January 23, 2019

As a leader on seismic safety and resilience, the City and County of San Francisco is advancing critical policies to strengthen its high-rise buildings and the densely occupied neighborhoods where they exist. Citywide preparation for the next big earthquake remains one of our top civic priorities. According to the U.S. Geological Survey (USGS), it is estimated that San Francisco has a 72 percent chance of experiencing a 6.7 magnitude or greater earthquake before 2043.

Conversations about vulnerabilities and safety improvements often occur after we learn from the lessons of the most recent disaster. To improve this process, the City convened an Executive Panel including the City Administrator, Directors of Building Inspection and Emergency Management, the Chief Resilience Officer, and the Public Utilities Commission. Working with experts from the nonprofit Applied Technology Council (ATC), the Panel studied San Francisco's tall buildings and made recommendations to improve the city's preparedness and ability to recover in the event of a major earthquake.

Our best line of defense against the effects of the next big earthquake is to prepare and strengthen the integrity and resilience of the city's infrastructure, neighborhoods, and residents. The Tall Building Safety Strategy is the latest effort to achieve this goal and to ensure preparedness. It builds on leading efforts such as the Community Action Plan for Seismic Safety (CAPSS), a report and 30-year work plan initiated after the Loma Prieta earthquake to understand and mitigate earthquake risks in San Francisco. CAPSS is implemented through the City Administrator's Earthquake Safety Implementation Program (ESIP).

San Francisco must continue to be proactive in maintaining its best practices of seismic safety and resiliency, and continue to push for better preparation for the next big earthquake.

Directives

Through this Executive Directive, I hereby direct:

1. That the City Administrator and the Directors of Emergency Management, Department of Building Inspection, and Planning Department conduct community outreach to inform City stakeholders about the Tall Buildings Safety Strategy. This outreach must ensure that property

owners, building tenants, engineering experts, and community leaders have the opportunity to inform and shape the implementation of the recommendations contained in the strategy.

- **2.** That the Building Inspection Commission and Department of Building Inspection develop additional regulations to address geotechnical and other engineering issues and to explore adopting higher seismic design standards.
- **3.** That the Department of Emergency Management, in conjunction with the Departments of Building Inspection and Public Works, update the policies and procedures for implementing the State's Safety Assessment Program and clarify department roles and responsibilities for post-earthquake emergency response and safety inspection. This work should be presented at the Disaster Council no later than July 1st of this year.
- **4.** That the City Administrator, through the Office of Resilience and Capital Planning and the Director of Emergency Management establish a Disaster Recovery Task Force that will develop San Francisco's recovery framework before a disaster. San Francisco's recovery framework should include a comprehensive recovery plan for the Financial District and adjacent neighborhoods no later than January 1, 2020. The Task Force should include public agencies, elected representatives, community based organizations and the private sector.
- **5.** That the City Administrator, through the Office of Resilience and Capital Planning, and Director of Emergency Management, in conjunction with my office, provide information and knowledge sharing with other cities facing similar seismic challenges and that are home to tall buildings.

This Executive Directive will take effect immediately, and will remain in place until rescinded by future written communication.



Introduction


In 2011, the City and County of San Francisco published the CAPSS Earthquake Safety Implementation Program Workplan 2012-2042 as a result of the Community Action Plan for Seismic Safety (CAPSS) in response to Mayor Newsom's Executive Directive 10-022. Workplan 2012-2042 anticipates programs for broad groups of new and existing buildings throughout the City. Looking ahead, the City recognized that within each broad group, some buildings would need special attention through exemptions, programmatic solutions, or specific technical criteria, to make the work feasible.

One such subgroup comprises the City's "tall buildings." In tall buildings, difficult exterior access, multiple tenants and uses within a building, and their sheer size complicate evaluation and retrofit. Their structural systems preclude generic performance assumptions and prescriptive engineering solutions. Damage to a tall building can pose risks well beyond its own footprint. Perhaps most important, San Francisco's new and existing tall buildings represent a dominant portion of the City's business sector, and increasingly house residents as well. Their high concentration downtown poses an aggregate risk to neighborhood and citywide recovery not presented by other building groups.

For these reasons, the City and County of San Francisco initiated the first project in the nation to consider the impact of earthquakes on a city's tall buildings. The project conducted investigations in seven focus areas under separate tasks. This report documents the complete findings and recommendations of each task, and the recommendations are summarized below.

An inventory developed for the project identified 156 buildings that are 240 feet or taller, either constructed or permitted for construction, primarily located in San Francisco's northeast neighborhoods (Supervisorial Districts 3 and 6). Approximately 60% of these buildings contain primarily business uses, while the others are predominantly residential. The recommendations presented here flow from a study of these tall buildings, but most are also applicable to a wider set of buildings supporting similar functions or posing similar risks. Tall buildings, even in downtown San Francisco, are only part of a neighborhood's building stock, and from a public policy perspective, their earthquake performance is bound up with that of the shorter buildings around them.

Each recommended action identifies one or more City departments to lead its implementation. However, implementation of any new policy is assumed to involve appropriate coordination with other City departments, outside experts (as needed), and other stakeholders. Some recommended actions require enactment of legislation by the Mayor and Board of Supervisors or action by the Building Inspection Commission and can only commence after these approvals.





Enhanced general inventory (Districts 3 and 6). Source: DataSF

Tall Buildings (over 240 feet)

Sections 1 through 4 below summarize the findings from the study in issue statements and describe the associated recommendations to address the issue. Section 5 presents the recommendations in a table format showing different aspects of each recommendation, including potential implementation timeframe, relationship to the Workplan 2012-2042, City department responsible for implementation, and the relationship of Summary Recommendations to Parts of the project report for reference.

Please note that the Summary Recommendations originally published as a part of the Tall Buildings Safety Strategy on October 4, 2018, have been updated in response to feedback from the structural engineering community. The specific changes are noted within the relevant recommendations.





Actions for Reducing Seismic Risk Prior to Earthquakes - New Buildings

1A. Develop Regulations to Address Foundation and Geotechnical Issues

Issue: The *San Francisco Building Code* sets minimum requirements for geotechnical site investigations and foundation design. Because they are minimum requirements, they do not fully address all of the geotechnical conditions found in San Francisco. Over the past several decades, the San Francisco geotechnical community has developed best practices for geotechnical evaluation and foundation design, but these are not yet codified. Many of the new tall building developments are challenging even these best practices due to unique soil conditions, the size and weight of the new buildings, and the sophisticated site investigation and the analysis approaches being used to assess overall building behavior, including building response to extreme earthquake ground motions.

Recommendation: To help reduce the risk associated with these geotechnical challenges, the Department of Building Inspection (DBI) should develop an Administrative Bulletin or Information Sheet (with building code amendments as needed) with acceptable practices on topics including the following:

- Settlement design and analysis criteria,
- Quality Assurance/Quality Control for foundation systems,
- Foundation design and other countermeasures for soil liquefaction and lateral spreading,
- · Shoring and dewatering design and analysis criteria,
- Lateral earthquake resistance of deep and shallow foundations, and
- Site characterization and exploration.

In addition, to strengthen DBI procedures for assessing the completeness of the foundation and excavation design for tall buildings, two actions are recommended:

- Increase DBI's expertise on geotechnical issues related to tall buildings through enhanced training and staffing.
- Develop a geotechnical report checklist to help ensure the completeness of the submitted geotechnical investigation, design, and field monitoring reports.

1B. Establish Recovery-Based Seismic Design Standards

Issue: San Francisco Building Code requirements for earthquake design, including the performance-based requirements of Administrative Bulletin 083, Requirements and Guidelines for the Seismic Design of New Tall Buildings Using Non-Prescriptive Seismic-Design Procedures, are primarily intended to provide acceptable safety in extreme earthquakes. Studies conducted in this project estimate that for a tall building designed to current standards, it might take two to six months to mobilize for and repair damage from a major earthquake, depending on the building location, geologic conditions, and the structural and foundation systems. Long downtimes in tall buildings can have disproportionate harmful effects on residents and businesses in San Francisco. By the City's tentative recovery goals, even three months of downtime is unacceptably long for major employers and other recovery-critical uses.

Recommendation: To shorten downtime in new tall buildings, DBI should develop an Administrative Bulletin (with building code amendments as needed) that supports the implementation of the City's tentative recovery goals and specifies recovery-based seismic design and construction requirements, including tighter drift limits under expected ground motions, enhanced design criteria for critical mechanical, electrical, plumbing, and elevator systems, enhanced detailing requirements for exterior cladding and interior partition walls, and measures to mitigate externalities that impede recovery. San Francisco's Building Occupancy Resumption Program (BORP) is designed to address some of these externalities (see recommendation 3B). BORP, or a program like it, should be required for all new tall buildings.





2. Actions for Reducing Seismic Risk Prior to Earthquakes – Existing Buildings

2A. Apply the Repair Provisions of the San Francisco Existing Building Code with Respect to Possible Loma Prieta Damage

Issue: The 1994 Northridge earthquake revealed unexpected damage to dozens of welded steel moment frame structures throughout the greater Los Angeles area (some of which were tall; most of which were not). In most cases, the structural damage did not reveal itself through evident architectural damage or noticeable changes under everyday use. Five years earlier, without the benefit of the lessons later learned in Northridge, San Francisco's steel buildings were not consistently inspected after the Loma Prieta earthquake. Ground motion data in downtown San Francisco during the Loma Prieta earthquake are limited and recorded data are lower than ground motions associated with connection damage in the Northridge earthquake. However observational data suggest that some areas of San Francisco experienced higher levels of shaking, potentially causing some buildings to sustain connection damage that went undetected.

Recommendation: DBI should develop a new Administrative Bulletin to interpret provisions of the *San Francisco Existing Building Code* as they apply to post-earthquake inspection and evaluation of welded steel moment frames. The Administrative Bulletin should be developed in a community consensus process used to define appropriate ground motion triggers and other indicators of potential damage. This process should consider all currently available information, including FEMA 352, *Recommended Postearthquake Evaluation and Repair Criteria for Welded Steel Moment-Frame Buildings*, available recorded and observational data on ground motions from the Loma Prieta earthquake, and information from building inspections that have occurred since the Loma Prieta earthquake. (Development of the Administrative Bulletin should be coordinated with related work described in Recommendation 3F.)

Using the resulting Administrative Bulletin, DBI should apply the repair provisions of the *San Francisco Existing Building Code* with respect to possible Loma Prieta damage. Because the enforcement would be taking place so long after the damaging earthquake, it would likely benefit from a special program including notification, guidance to owners and tenants, appropriate deadlines, and consideration of voluntary inspection and repair work already performed. This Administrative Bulletin can also be used in the implementation of *Workplan 2012-2042* Task C.2.d, evaluation and retrofit of all pre-1994 welded steel moment frame buildings.

Recommendation 2A was modified to include a clarification that the repair provisions of the San Francisco Existing Building Code should be applied in accordance with a

future Administrative Bulletin that defines appropriate triggers and other indicators of potential damage.

2B. Amend the San Francisco Existing Building Code Triggers

Issue: San Francisco has its own set of code provisions that trigger seismic upgrade when building alterations or changes of occupancy exceed a certain scope. Because they apply only when two-thirds of a building's floors are altered or the occupant load is significantly increased, they almost never apply to tall buildings, and are easily avoided. Therefore, even the most collapse-prone tall buildings almost never receive the scrutiny intended by the code. That said, since the retrofit of an occupied tall building is especially expensive and disruptive, a more aggressive trigger provision could discourage modernization, tenant improvement, or adaptive reuse. Thus, the *San Francisco Existing Building Code*'s generic provisions are problematic for tall and similarly large or complex facilities.

Federal and State government agencies, as well as some private institutions, also trigger seismic evaluation, and possibly retrofit, when a facility is purchased or leased. As contemplated in Workplan 2012-2042, San Francisco could supplement its rarely used alteration and change of occupancy triggers with such an acquisition trigger. Understanding that triggered retrofits of tall buildings can be unreasonably expensive and disruptive, acquisition-based triggers for just evaluation would at least ensure that buildings are properly valued with respect to the risks they pose to owners and tenants.

Recommendation: As the *San Francisco Existing Building Code* is amended to coordinate with the 2019 California codes, the Building Inspection Commission (BIC) should consider revisions that would find the right balance between the triggers and the triggered scope from an alteration. This could include setting a lower trigger, such as evaluation and disclosure, for most tall buildings and reserving a higher trigger, such as mandatory retrofits for those most prone to collapse. BIC should also consider adding triggers that apply when buildings are purchased or leases are renewed. For purposes of resilience and recovery planning, triggered evaluations might be required to include an estimate of recovery time as well as safety.

Recommendation 2B was expanded to include the addition of triggers that apply when buildings are purchased or leases are renewed. In addition, the issue statement was expanded to include change of occupancy triggers.

2C. Recommend Minimum Levels of Earthquake Insurance or Other Collateral to Ensure Post-earthquake Recovery


Issue: Available information suggests that earthquake insurance availability and market penetration for commercial and residential buildings are low. Furthermore, when available, the insurance coverage is often limited to a small fraction of the building replacement cost, raising questions about the ability to repair and recover after a damaging earthquake. Insurance or other resources to cover losses suffered by the neighbors of a tall building or costs to the City (for debris removal or emergency protective measures) are also unclear.

Recommendation: The City should identify potential limitations on the availability of financial capital after a damaging earthquake and recommend minimum levels of insurance (or other collateral) for tall building owners to ensure recoverability of their buildings and the neighboring community.

2D. Review Requirements for Post-earthquake Fire Suppression and Evacuation Systems

Issue: Tall buildings rely on automatic fire suppression systems (typically sprinklers) to inhibit fire spread and allow time for evacuation. Automatic fire suppression will be particularly important following a significant earthquake, when risk of fire ignitions might be higher, and the response time of fire departments might be longer than usual. Normally, sprinkler systems in high-rise buildings use water from the City's municipal system, pressurized with pumps and emergency generators. Recognizing the risk that the City water supply may be disrupted by an earthquake, the *San Francisco Building Code* requires many buildings to have an in-building secondary water supply to operate the sprinkler system for 30 minutes.

Recommendation: The San Francisco Fire Department (SFFD) and the Department of Emergency Management (DEM) should coordinate a study to evaluate the adequacy of automatic fire suppression and occupant evacuation systems in tall buildings for conditions following a significant earthquake. The study should be coordinated with other City departments and within the broader context of the *San Francisco Emergency Response Plan* to evaluate whether (1) the in-building secondary water supply for automatic fire suppression in tall buildings is sufficient to inhibit fire spread and allow safe evacuation, and (2) the building code provisions that rely on elevators for evacuation during a fire emergency will be effective following an earthquake. The study should develop requirements and recommendations for the *San Francisco Building Code and Emergency Response Plan* to address any significant limitations or risks that are identified.



3. Actions for Reducing Seismic Risk Following Earthquakes

3A. Develop New Policies and Procedures for Implementing the State's Safety Assessment Program

Issue: The Safety Assessment Program (SAP), through which volunteer inspectors "post" buildings with red, yellow, or green placards, is run by the California Office of Emergency Services (Cal OES). DBI is charged with implementing San Francisco's participation in the program. The SAP procedures and criteria are based on ATC-20, Procedures for *Postearthquake Safety Evaluation of Buildings*, and are generic and not well-suited to complex or recovery-critical facilities, including most tall buildings.

Recommendation: DBI should develop its own procedures suited to San Francisco's tall buildings (and otherwise unique building stock) regarding such topics as limits on exterior-only inspection, limits on rapid evaluation, damage estimates, placard use, and placard text.

In coordination with its implementation of SAP, DBI should also develop a plan to use specially qualified SAP volunteers to inspect pre-selected groups of buildings, one of which might be tall buildings, especially those not covered by BORP. More generally, the building groups of interest should be related to the City's adopted recovery goals. These specially trained and assigned inspection teams would facilitate recovery of building types with fast recovery goals.

3B. Extend and Improve the Building Occupancy Resumption Program

Issue: BORP, created by DBI, allows building owners to arrange in advance for post-earthquake safety inspections using their own contracted inspectors. Participation is voluntary. DBI approves each participating building's application and pre-certifies the owner's inspection team. Most of the current BORP participants are downtown office buildings. BORP solves many of the problems associated with applying the general Safety Assessment Program to tall or otherwise complex or recovery-critical buildings. To enhance BORP's effectiveness and to derive the most value from it, DBI should maintain and update the program.

Recommendation: DBI should enhance the BORP program with the following:

 Conduct simulation-based training to ensure readiness of building staff, BORP-certified inspectors, and DBI staff.

- Update the BORP instructions and procedures to improve consistency and practicality. In particular, material required for certification by DBI should be separate from material to be used by the BORP inspection team in the field. The field material should be organized to align with the ATC-20 evaluation procedures already adopted by BORP as its standard.
- Add specific criteria and pre-earthquake procedures to facilitate implementation of FEMA 352, Recommended Postearthquake Evaluation and Repair Criteria for Welded Steel Moment-Frame Buildings, for welded steel moment frame structures.
- Require BORP for all new tall buildings. The program should be extended through
 incentive programs, triggers, and possibly even mandates (see recommendations
 1B and 3H) for certain tall or otherwise recovery-critical buildings. The purpose
 would be to require at least a basic recovery plan, if not full BORP documentation
 and implementation, for a larger set of existing buildings.
- Together with ORCP, extend the BORP scope to support functional recovery in addition to safe reoccupancy. For tall buildings, this might include additional procedures for individual tenant spaces.

3C. Clarify and Update Roles and Responsibilities Associated with Post-earthquake Emergency Response and Safety Inspection

Issue: Current procedures and practices for post-earthquake emergency response and safety inspection are inconsistent, and sometimes out of date, regarding the roles of certain City departments and their interaction with state-level programs and private sector plans (including BORP).

Recommendation: DEM, in coordination with DBI and Public Works, should update the *Earthquake Annex of the San Francisco Emergency Response Plan* regarding activation of the Cal OES Safety Assessment Program.

DBI and Public Works should also update their SAP and BORP procedures regarding the division of responsibility and criteria for establishing cordons and barricades, in coordination with Lifelines Council recommendations for priority transit routes. (See also recommendation 3G.)

3D. Update and Amend the San Francisco Existing Building Code Triggers for Repair Projects

Issue: The San Francisco Existing Building Code triggers for seismic upgrade based on the extent of earthquake damage, originally pioneered by San Francisco, have fallen out of coordination with the latest state code. In addition, while the latest requirements are rational for most buildings, for larger structures they can become disproportionately expensive and disruptive. If repairs to many large buildings are triggered, the aggregate impact can affect the City's overall recovery. San Francisco's code amendments might exacerbate the problem by not allowing use of reduced loads typical for retrofits.

Recommendation: As the 2019 California code becomes effective, DBI should take the opportunity to update its traditional amendments and coordinate them with the state code.

Regarding repair-triggered retrofits, ORCP, together with appropriate BIC committees, should investigate whether San Francisco should relax its code provisions for certain buildings, especially regarding the "substantial structural damage" trigger. The study should consider typical San Francisco buildings, ideally with a scenario that considers the effects of multiple buildings on downtown recovery.

3E. Update Administrative Bulletin 099 and Clarify its Application to Tall Concrete Structural Systems

Issue: Administrative Bulletin (AB) 099, *Post-earthquake Repair and Retrofit Requirements for Concrete Buildings*, supplements the San Francisco Existing Building Code by implementing FEMA 306, Evaluation of Earthquake Damaged Concrete and Masonry Wall Buildings, published in 1998. Many of AB-099's references are due for updates. Further, while AB-099 applies to all concrete buildings, some of its provisions might prove difficult to apply to tall buildings.

Recommendation: DBI should update AB-099 to coordinate with newer building code provisions and reference standards. DBI should also develop a commentary to the updated AB-099 to guide its application to tall and otherwise complex concrete buildings.

3F. Develop a New Administrative Bulletin for Post-earthquake Inspection and Evaluation of Welded Steel Moment Frames

Issue: Many of San Francisco's tall buildings have welded steel moment frames as their structural systems. FEMA 352, *Recommended Postearthquake Evaluation and Repair Criteria for Welded Steel Moment-Frame Buildings*, was developed after the 1994 Northridge earthquake specifically for this structure type, but it is not fully referenced by San Francisco codes and procedures.

Recommendation: DBI should develop an Administrative Bulletin to implement FEMA 352. If code amendments are necessary, DBI should work with the Mayor, Board of Supervisors, and the Building Inspection Commission to approve them.

For post-earthquake safety evaluation, the recommended Administrative Bulletin should clarify the procedures and criteria that DBI will accept in coordination with Rapid and Detailed Evaluations using ATC-20. (As noted in recommendation 3B, FEMA 352 is already allowed by BORP, but the program procedures are incomplete regarding its use, so the recommended AB could address that shortcoming as well.)

For post-earthquake application of upgrade triggers, just as AB-099 supplements the *San Francisco Existing Building Code* for concrete buildings, a similar bulletin should be developed for welded steel moment frames, which are even more common in San Francisco's tall buildings.

3G. Create Protocols and Procedures for Establishing Cordons around Damaged Buildings

Issue: Cordons or barricades are often needed to protect the areas around a damaged building. The cordoned area is generally based on the perceived level of damage and the risks posed by potential aftershocks, wind loading, time-dependent creep effects, or other factors. While cordons may be required around buildings of any height, the disruptive implications of current generic guidance for cordon distance increase dramatically with building height, potentially leading to unnecessary closure of neighboring buildings and infrastructure.


3.

Recommendation: DPW, in coordination with DBI (see recommendation 3C) should develop protocols and procedures for cordoning around damaged buildings. The procedures should be based on current practices but should also account for tall building effects on neighborhood safety and recovery, as well as new information regarding aftershock risks and early warning.

3H. Require Existing Buildings to File Recovery Plans

Issue: Because aggressive retrofit triggers and mandates can be unreasonably expensive and disruptive for occupied tall buildings, thorough recovery planning is a more feasible alternative. BORP can facilitate recovery in a lightly damaged building, but as a voluntary program, it is not used widely enough to improve the recovery of a whole neighborhood like San Francisco's downtown, where the City's tall buildings are most densely clustered.

Recommendation: ORCP, in coordination with DBI, should identify buildings critical to the City's recovery and mandate the filing of building information, and possibly a basic recovery plan, with the City. The building information would enhance existing databases and inform the City's response and recovery planning, and the building-specific recovery plan would be a way of extending the benefits of BORP without requiring ongoing expense from owners.



4. Actions to Improve the City's Understanding of its Tall Building Seismic Risk

4A. Maintain and Expand the Database of Tall Buildings

Issue: This project compiled a database with information about all buildings 240 feet or taller, either constructed or currently permitted for construction, in San Francisco. The database includes information on building location, height, occupancy, age, construction material, structural system, year of retrofit, and foundation type. Prior to the creation of this database, the City had no centralized, searchable repository with this information about all tall buildings in its jurisdiction. Following the completion of this project, the City will need to develop a mechanism for maintaining or expanding the database.

Recommendation: As the owner of the database, ORCP should work with DataSF and DBI to maintain and expand the tall building database. Specific recommended actions include:


- Develop mechanisms for harvesting building data from building permits or inspections administered by DBI or other agencies. For example, San Francisco Existing Building Code Chapter 4E will yield information on building façades as the provisions are implemented over the coming years.
- Make the database available for public review and use. This will encourage updates by building owners and will facilitate use of the data in studies to promote recovery and resilience planning.
- Expand the database to include the following:
 - All buildings taller than 75 feet. As described in the project report, the 240-foot height criterion for the initial database was somewhat arbitrary. To the extent that the San Francisco Building Code imposes elevator, fire safety, and other requirements on high-rise buildings defined as those taller than 75 feet, it would be useful to expand the database to include at least all buildings above this height.
 - Specific building uses by industry or employment sector. The data should be coordinated with development of the City's overall recovery goals. Ideally, similar data for non-tall buildings serving those same recovery functions would also be compiled, allowing a better understanding of the tall building effects in terms of neighborhood and citywide recovery.
 - Foundation type of any building on a site mapped as susceptible to liquefaction.

4B. Develop a Comprehensive Recovery Plan for the Financial District and Adjacent Neighborhoods

Issue: The present study addresses the effect of tall building damage on the tall buildings themselves and, to a lesser extent, on the downtown neighborhoods where tall buildings are densely clustered and on the City overall. But it does not explicitly address the likely interactions between the tall buildings, the non-tall buildings that still comprise most of downtown, and the critical infrastructure that serves the neighborhood. Nor does it explicitly consider resource demands and capacities of the businesses, residents, workers, and other stakeholders.

Recommendation: A separate recovery plan, drawing on the present study's findings, would bring these ideas together in a practical way to support a neighborhood and its functions, as opposed to just individual buildings with certain characteristics. An interim recovery plan, which should be developed by the City Administrator, would need to make many assumptions. This should be followed by a more thorough recovery study to confirm or correct those assumptions and to fill in the most critical knowledge gaps. Such a study would address the combined effects of tall buildings, non-tall buildings, and infrastructure, including liquefaction effects. The study would develop a recovery curve estimating the level of immediate functional loss and the extent of re-occupancy and recovery over time following one or more scenario earthquakes.

The recovery plan should consider developing alternative habitability standards for tall buildings. In 2012, SPUR recommended relaxing normal habitability standards during post-earthquake recovery, gradually returning to a state of normalcy. But the SPUR recommendations were developed primarily for houses and wood-frame apartment buildings. Tall buildings, by contrast, rely on sophisticated systems for heating, ventilation, air conditioning, elevators, and fire suppression, so the SPUR recommendations will not apply. DEM, together with ORCP, should develop alternative recovery-phase habitability standards for tall buildings, considering minimum requirements for fire barriers, suppression and safety systems, vertical transportation, water services, and electricity.



Building Stock: Downtown Context

Compiled from tax assessor and building footprint data avaiable at DataSF.org

Height (ft)

> 240

160 - 240

75 - 160

< 75

Study Area

☐ Miles 0.5 N

Tall Building Occupancies

SUMMARY TABLES



Summary Tables

Table S-1: Implementation Timeframe

Table S-1 presents the recommendations in terms of potential implementation timeframes. Short-term actions can be started with essentially no additional study and completed without a legislative process. Typical examples include administrative updates, development of Administrative Bulletins, and initiatives requiring only nominal interdepartmental coordination. Mid-term actions can normally be completed without substantial additional study and without a legislative process but are expected to involve substantial input from multiple stakeholder groups. Long-term actions are expected to require substantial additional technical study or a legislative process.

Recommended Action	SHORT- TERM	MID- TERM	LONG- TERM				
1. Actions for Reducing Seismic Risk Prior to Earthquakes - New Buildings							
1A. Develop Regulations to Address Foundation and Geotechnical Issues							
Training and checklist	Х						
Develop geotechnical regulations		Х					
1B. Establish Performance-Based Seismic Design Standards							
2. Actions for Reducing Seismic Risk Prior to Earthque Buildings	ıakes - I	Existing					
2A. Apply the Repair Provisions of the San Francisco Existing Building Code with Respect to Possible Loma Prieta Damage		Х					
2B. Amend the San Francisco Existing Building Code							
Alteration and change of occupancy triggers	Х						
Acquisition triggers		Х					
2C. Recommend Minimum Levels of Earthquake Insurance or Other Collateral to Ensure Post-earthquake Recovery			Х				
2D. Review Requirements for Post-earthquake Fire Repression and Evacuation Systems		Х					

Table S-1: Implementation Timeframe

Recommended Action	SHORT- TERM	MID- TERM	LONG- TERM
3. Actions for Reducing Seismic Risk Following Earth	nquakes		
3A. Develop New Policies and Procedures for Implementing the State's Safety Assessment Program	Х		
3B. Extend and Improve the Building Occupancy Resumption Program			
Conduct simulation-based training	X		
Update procedures	X		
Extend program		Х	
3C. Clarify and Update Roles and Responsibilities Associated with Post-earthquake Emergency Response and Safety Inspection	X		
3D. Update and Amend the San Francisco Existing Building Code Triggers for Repair Projects		Х	
3E. Update Administrative Bulletin 099 and Clarify its Application to Tall Concrete Structural Systems			X
3F. Develop a New Administrative Bulletin for Post-earthquake Inspection and Evaluation of Welded Steel Moment Frames			X
3G. Create Protocols and Procedures for Establishing Cordons Around Damaged Buildings	Х		
3H. Require Existing Buildings to File Recovery Plans			Х
4. Actions to Improve the City's Understanding of its Risk	Tall Bui	ilding Se	eismic
4A. Maintain and Expand the Database of Tall Buildings	Х		
4B. Develop a Comprehensive Recovery Plan for the Financial District and Adjacent Neighborhoods			Х

Table S-2: Relationship of Recommended Actions to Workplan 2012-2042 Tasks

Table S-2 relates the recommendations relevant to tasks in *Workplan 2012-2042*. In some cases, this tall building study identified additional programs and initiatives not detailed in *Workplan 2012-2042*. In others, the tall building recommendations identify specific technical criteria, exemptions, or programmatic solutions suitable for tall and similarly complex buildings, even relaxing some of the *Workplan 2012-2042*'s broad directives.

Recommended Action	Workplan 2012-2042 Task						
1. Actions for Reducing Seismic Risk Prior to Earthquakes - New Buildings							
1A. Develop Regulations to Address Foundation and Geotechnical Issues	New action						
1B. Establish Recovery-Based Seismic Design Standards	B.6.a Update code for new buildings to reflect desired performance goals						
2. Actions for Reducing Seismic Risk Price Buildings	or to Earthquakes - Existing						
2A. Apply the Repair Provisions of the San Francisco Existing Building Code with Respect to Possible Loma Prieta Damage	B.4.b Develop post-earthquake repair and retrofit standards						
2B. Amend the San Francisco Existing Building Code Triggers	 C.1.a Mandatory evaluation on sale or by deadline C.1.b Evaluation of buildings retrofitted prior to 1994 or building to non-conforming performance standards C.2.a Mandatory retrofit of older non-ductile concrete residential buildings C.2.d Mandatory evaluation and retrofit of pre-1994 welded steel moment frame buildings C.2.e Mandatory evaluation and retrofit of other low-performance buildings 						
2C. Recommend Minimum Levels of Earthquake Insurance or Other Collateral to Ensure Post-earthquake Recovery	A.1.b Provide information and assistance about insurance						
2D. Review Requirements for Post-Earthquake Fire Suppression and Evacuation Systems	A.6.i Study fire-related earthquake resilience topics						

Table S-2: Relationship of Recommended Actions to Workplan 2012-2042 Tasks

Recommended Action	Workplan 2012-2042 Task							
3. Actions for Reducing Seismic Risk Following Earthquakes								
3A. Develop New Policies and Procedures for Implementing the State's Safety Assessment Program	A.4.f Update post-earthquake inspection (ATC-20) policies and procedures							
3B. Extend and Improve the Building Occupancy Resumption Program	B.1.b Develop non-structural upgrade program for businesses							
3C. Clarify and Update Roles and Responsibilities Associated with Post-earthquake Emergency Response and Safety Inspection	Procedural update							
3D. Update and Amend the San Francisco Existing Building Code Triggers for Repair Projects	B.4.b Develop post-earthquake repair and retrofit standards							
3E. Update Administrative Bulletin 099 and Clarify its Application to Tall Concrete Structural Systems	A.4.d Adopt disproportionate damage trigger B.4.b Develop post-earthquake repair and retrofit standards							
3F. Develop a New Administrative Bulletin for Post-earthquake Inspection and Evaluation of Welded Steel Moment Frames	A.4.d Adopt disproportionate damage trigger B.4.b Develop post-earthquake repair and retrofit standards							
3G. Create Protocols and Procedures for Establishing Cordons around Damaged Buildings	Program update, new action							
3H. Require Existing Buildings to File Recovery Plans	B.1.b Develop non-structural upgrade program for businesses							
4. Actions to Improve the City's Understan	ding of its Tall Building Seismic Risk							
4A. Maintain and Expand the Database of Tall Buildings	A.2.b Adopt façade maintenance regulations							
4B. Develop a Comprehensive Recovery Plan for the Financial District and Adjacent Neighborhoods	 A.4.a Develop and adopt Shelter-in-Place policies and procedures B.2.b Mandatory evaluation of 5+ dwelling unit residential buildings and hotels/motels C.2.b Mandatory evaluation and retrofit of critical stores, suppliers, and service providers C.2.c Mandatory evaluation and retrofit of larger (over 300 occupants) assembly buildings 							

Table S-3: Responsible Department

Table S-3 presents the recommendations in terms of City departments responsible for implementation. The departments are identified as follows:

Representative Organization	Abbreviation
Building Inspection Commission	BIC
DataSF	
Department of Building Inspection	DBI
Department of Emergency Management	DEM
Department of Public Works	DPW
Office of Assessor-Recorder	OAR
Office of Resilience and Capital Planning	ORCP
San Francisco Fire Department	SFFD

Recommended Action	BIC	DATASF	DBI	DEM	DPW	OAR	ORCP	SFFD
1. Actions for Reducing Seismic Risk Prior to Earthquakes - New Buildings							gs	
1A. Develop Regulations to Address Foundation and Geotechnical Issues			Х					
1B. Establish Performance-Based Seismic Design Standards			Х					
2. Actions for Reducing Seismic Risk Price Buildings	or to	Eartl	hqua	kes	- Exi	sting	l	
2A. Apply the Repair Provisions of the San Francisco Existing Building Code with Respect to Possible Loma Prieta Damage			Х					
2B. Amend the San Francisco Existing Building Code Triggers	Х					Х		
2C. Require Minimum Levels of Earthquake Insurance or Other Collateral to Ensure Post-earthquake Recovery			Х					
2D. Review Requirements for Post-earthquake Fire Suppression and Evacuation Systems			Х					Х

Table S-3: Responsible Department

Recommended Action	BIC	DATASF	DBI	DEM	DPW	OAR	ORCP	SFFD
3. Actions for Reducing Seismic Risk Following Earthquakes								
3A. Develop New Policies and Procedures for Implementing the State's Safety Assessment Program			Х					
3B. Extend and Improve the Building Occupancy Resumption Program			Х				Х	
3C. Clarify and Update Roles and Responsibilities Associated with Post-earthquake Emergency Response and Safety Inspection			X	X	Х			
3D. Update and Amend the San Francisco Existing Building Code Triggers for Repair Projects	Х		Х				Х	
3E. Update Administrative Bulletin 099 and Clarify its Application to Tall Concrete Structural Systems			х					
3F. Develop a New Administrative Bulletin for Post-earthquake Inspection and Evaluation of Welded Steel Moment Frames	Х		Х					
3G. Create Protocols and Procedures for Establishing Cordons around Damaged Buildings			Х	Х	Х			
3H. Require Existing Buildings to File Recovery Plans			Х				Х	
4. Actions to Improve the City's Understanding of its Tall Building Seismic Risk							ic	
4A. Maintain and Expand the Database of Tall Buildings		Х	Х				Х	
4B. Develop a Comprehensive Recovery Plan for the Financial District and Adjacent Neighborhoods				X			Х	

Table S-4: Recommended Actions by Part

Table S-4 presents the relationship of Summary Recommendations to Parts of the full report for reference. A copy of the full copy of the report is available for download at onesanfrancisco.org/esip.

Recommended Action	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7
1. Actions for Reducing Seismic Risk Prior to	Eartl	nqua	kes -	- Ne	w Bu	ilding	gs
1A. Develop Regulations to Address Foundation and Geotechnical Issues		Х					
1B. Establish Performance-Based Seismic Design Standards			Х				
2. Actions for Reducing Seismic Risk Prior to Earthquakes - Existing Buildings							
2A. Apply the Repair Provisions of the San Francisco Existing Building Code with Respect to Possible Loma Prieta Damage						X	
2B. Amend the San Francisco Existing Building Code Triggers							Х
2C. Require Minimum Levels of Earthquake Insurance or Other Collateral to Ensure Post-earthquake Recovery					Х		
2D. Review Requirements for Post-earthquake Fire Suppression and Evacuation Systems					Х		
3. Actions for Reducing Seismic Risk Followi	ng Ea	artho	luake	es			
3A. Develop New Policies and Procedures for Implementing the State's Safety Assessment Program					х	х	
3B. Extend and Improve the Building Occupancy Resumption Program						Х	
3C. Clarify and Update Roles and Responsibilities Associated with Post-earthquake Emergency Response and Safety Inspection					х	Х	

Table S-4: Recommended Actions by Part

Recommended Action	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7
3D. Update and Amend the San Francisco Existing Building Code Triggers for Repair Projects				Х			
3E. Update Administrative Bulletin 099 and Clarify its Application to Tall Concrete Structural Systems				Х			
3F. Develop a New Administrative Bulletin for Post-earthquake Inspection and Evaluation of Welded Steel Moment Frames				Х		х	
3G. Create Protocols and Procedures for Establishing Cordons around Damaged Buildings					х		
3H. Require Existing Buildings to File Recovery Plans							Х
4. Actions to Improve the City's Understandi Risk	ng of	its 1	Tall B	uild	ing S	eism	ic
4A. Maintain and Expand the Database of Tall Buildings	х						
4B. Develop a Comprehensive Recovery Plan for the Financial District and Adjacent Neighborhoods						х	

Tall Buildings Safety Strategy Stakeholders

Interest Group	Representative Organization
Board of Supervisors	District 3
	District 6
Private Engineers and Architects	DBI Code Advisory Committee
	Heller Manus Architects
	Building Inspection Commission
	НОК
	Maffei Structural Engineering
	BXP
	SEAONC AB 82/83 Code Advisory Committee
	Fennie+Mehl Architects
Developers	San Francisco Apartment Owners Association
	Tishman Speyer
	Boston Properties
Business	San Francisco Chamber of Commerce
Real Estate	Real Estate Advisory Services
Community and Non-profit Organizations	SPUR
	BOMA
	The East Cut Community Benefit District
City and County of San Francisco Staff	Department of Building Inspection
	Real Estate Division
	Department of Emergency Management
	Planning Department
	Fire Department
	SFPUC
	Public Works
	Office of Resilience and Capital Planning

